

STANDARD NOTICE OF WORK COMPLETED AND NOT COMPLETED

NOTICE - All recommendations may not have been completed - See Below - Recommendations not completed.
This form is prescribed by the Structural Pest Control Board.

Building No.	Street	City	Zip	Date of Completion
9999 W. Lefty Ln., Rightway City, CA 90009				11/29/2011
<div style="display: flex; align-items: center;"> <div style="flex: 1;"> <h2 style="margin: 0;">Your Pest Company inc.</h2> <p style="margin: 0;">1234 Your Street, City, CA 90000 (800) 337-2818 - www.aceapp.com</p> </div> </div>				Report #
				W20153
				Lic. Registration #
				PR 9999
				Escrow #
Ordered By:		Property Owner and/or Party of Interest:		Completion Sent To:
John Doe 9999 W. Lefty Ln. Rightway City, CA 90009		John Doe 9999 W. Lefty Ln. Rightway City, CA 90009		John Doe 9999 W. Lefty Ln. Rightway City, CA 90009

The following recommendations on the above designated property, as outline in Wood Destroying Pests and Organisms Inspection Report dated 11/22/2011 have been and/or have not been completed.

Recommendations completed by this firm that are in accordance with the Structural Pest Control Board's Rules and Regulations: 1A, 1B, 8A, 11A								
Recommendations completed by this firm that are considered secondary and substandard measures under Section 1992 of the Structural Pest Control Board's Rules and Regulations including person requesting secondary measure:								
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">Cost of work completed:</td> <td style="width: 40%; text-align: right;">Cost : <u>\$1,630.00</u></td> </tr> <tr> <td></td> <td style="text-align: right;">Inspection Fee : _____</td> </tr> <tr> <td></td> <td style="text-align: right;">Other : _____</td> </tr> <tr> <td></td> <td style="text-align: right;">Total : <u>\$1,630.00</u></td> </tr> </table>	Cost of work completed:	Cost : <u>\$1,630.00</u>		Inspection Fee : _____		Other : _____		Total : <u>\$1,630.00</u>
Cost of work completed:	Cost : <u>\$1,630.00</u>							
	Inspection Fee : _____							
	Other : _____							
	Total : <u>\$1,630.00</u>							
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 60%;">Recommendations not completed by this firm:</td> <td style="width: 40%; text-align: right;">Estimated Cost : _____</td> </tr> <tr> <td colspan="2" style="padding-top: 10px;"> 11B was/were not repaired by this company. The work visibly appears completed in a workmanlike manner. This company was not present at the time of repairs and has no knowledge of materials or quality of work performed, nor issues any warranty. </td> </tr> </table>	Recommendations not completed by this firm:	Estimated Cost : _____	11B was/were not repaired by this company. The work visibly appears completed in a workmanlike manner. This company was not present at the time of repairs and has no knowledge of materials or quality of work performed, nor issues any warranty.					
Recommendations not completed by this firm:	Estimated Cost : _____							
11B was/were not repaired by this company. The work visibly appears completed in a workmanlike manner. This company was not present at the time of repairs and has no knowledge of materials or quality of work performed, nor issues any warranty.								
Remarks: This is to certify that the property described herein is now free of evidence of active infestation or infection in the visible and accessible areas.								

Signature

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding two years upon payment of a search fee to: Structural Pest Control Board, 2005 Evergreen Street, Ste. 1500, Sacramento, California 95815.
NOTE: Questions or problems concerning the above report should be directed to the manager of this company. Unresolved questions or problems with services performed may be directed to the Structural Pest Control Board at (916) 561-8708, (800) 737-8188 or www.pestboard.ca.gov.